Coast-Valley Testing, Inc.

Order Number

46953

Reference Number

06-5873

Foundation Exploration

&

Liquefaction Analysis

For

Wright *Company

C/O Tony Bortolazzo

130 Garden Street

Santa Barbara, California 93101

Proposed

Residential Development

222 Santa Barbara Street

Santa Barbara, California 93101

March 27, 2006

TABLE OF CONTENTS

March 27, 2006

Order Number: 46953

Reference Number: 06-5873

		Page #
***	INTRODUCTION	1
+**	DESCRIPTION OF FIELD INVESTIGATION	1
***	AND LABORATORY TESTING	
***	FINDINGS	2
**	RECOMMENDATIONS	2 thru 4
***	APPENDIX-(THIS INCLUDES THE EARTH QUAKE DESIGN FACTORS)	5 thru 20

Order Number: 46953

Reference Number: 06-5873

INTRODUCTION

The proposed residential development is to be located at 222 Santa Barbara Street in Santa Barbara, California

as shown on Appendix #1. The site is presently developed with (2) existing structures. Site drainage is to the

South at slopes of 1 to 2 percent.

It is the purpose of this investigation to provide sufficient information about the soils in the supporting soil

mantle to enable a suitable foundation design for the proposed structure. This investigation does not include

analysis of any geological conditions such as: faults, fractures, potential geological movement, or slope

stability. This investigation was conducted in accordance with presently accepted soils engineering procedures

consistent with the proposed development and no warranty is implied.

FIELD INVESTIGATION

The subsurface soil conditions were explored by 4 truck mounted auger borings that were drilled to depths of

up to 50.0 feet below present ground surface. Soil samples were obtained during the drilling operations for

laboratory testing and analysis and the borings were supplemented by 4-field density test that was performed

by the tube method. The boring and density test locations are shown on Appendix # 1, while the boring data is

presented on Appendix # 2 thru # 5.

LABORATORY TESTING

Laboratory testing and analysis consisted of soil field moisture content summary, Maximum Density-

Optimum Moisture content determinations, field density summary, soil grain size analysis (mechanical

and hydrometer method), and soil expansion potential tests. The results of our laboratory testing are presented

in the Appendix.

Order Number: 46953

Reference Number: 06-5873

FINDINGS:

- 1. Ground water was encountered during the exploration at a depth of 7.0 to 8.5 feet below existing grade.
- 2. In general, the top <u>36 inches</u> of existing surface soils were found to be loose and porous becoming moderately firm to firm below this depth.
- 3. The existing surface soils were found to be slightly expansive.
- 4. At the time of this exploration surface vegetation consist of low grasses and weeds and planted landscape area.

LIQUEFACTION ANALYSIS:

Liquefaction is a process, which occurs when saturated sediments are subjected to repeated strain reversals, due to seismic events. The strain reversals cause an increase in pore water pressure, reducing the shear strength of the soil. Liquefied soils are subject to flow. Consolidation (ie settlement) or excessive strain. Liquefaction typically occurs in loose to medium dense sands and silty sands below the ground water table. Predominately fine-grained soils such as silts or clays are less susceptable to liquefaction. The liquefaction analysis at this site has been analyzed, utilizing the Seed's and Others Method (1985), and the Liquefy Pro Computer Program by "Civil Tech"). Uncorrected SPT readings were obtained by driving a standard 1 3/8-inch diameter split spoon sampler driven by a 140-pound hammer dropped 30 inches with an auto trip device. The percent finer than the 200 sieve has been determined by laboratory testing on representative soil samples. The SPT blow counts and percent passing the 200 sieve are presented on the Liquefaction Analysis in the attached appendix. Based on a magnitude 7.0 earthquake and a ground acceleration of 0.40g a potential for Liquefaction at this site was observed at depths between 18.0 and 25.0 feet below existing grade.

Order Number: 46953

Reference Number: 06-5873

RECOMMENDATIONS:

Total settlement was determined to be 1.14 inches while differential settlement was estimated between

0.57 to 0.75 inches. Both the computer-generated graphic and analytical analysis are presented in the

appendix.

The results of the Liquefaction Analysis indicates that the soils at this site are marginally liquefiable and

the total settlement (1.14 inches) and the total settlement (0.6 to 0.75 inches) are well within acceptable

limits for typical masonry, concrete or wood frame construction. Therefore, no additional measures other

than those required in this report (grading and foundation) are required to mitigate the hazards due to

Liquefaction.

RECOMMENDATIONS:

It is the understanding of this office that the site will be developed with 3-story wood frame residences, with

slab on grade floors as shown on Appendix #1. Based upon the results of our testing and liquefaction analysis,

this office recommends the following:

GRADING RECOMMENDATIONS:

1. Remove the existing structures including the foundation systems, and all existing underground man-made

facilities.

2. The area to be graded shall be cleared of surface vegetation, including roots and root structures.

3. Within the proposed building areas and for a minimum distance of 5.0 feet beyond the exterior perimeters

of the proposed structures, including porches and other appendages, the existing loose surface soils shall be

removed to a depth of 36 inches or 18 inches below the bottom of the proposed footings whichever is deeper.

4. The soil engineer shall inspect and approve the exposed cavity.

Continued-

5. Upon approval, the exposed cavity shall be scarified an additional 6 inches, moistened or dried to near

optimum moisture content and compacted to a minimum of 90 percent relative compaction, as tested and

certified by the soils engineer.

6. The Compaction Standard shall be the ASTM D 1557-91 Method of Compaction.

7. The removed soil, if free of deleterious material may then be replaced in lifts not to exceed 6 inches in

depth, moistened or dried to near optimum moisture content and compacted to a minimum of 90 percent

relative compaction, as tested and certified by the soil engineer.

8. Positive drainage shall be provided away from the proposed structures, (2 percent minimum for 5.0 feet).

9. In patio areas and walkways, the top 1.0 foot of subgrade soils shall be removed and recompacted to a

minimum of 90 percent relative compaction, as tested and certified by the soil engineer.

10. In driveways and/or parking areas, the top 24 inches of subgrade soils shall be compacted to a minimum of

95 percent relative compaction, as tested and certified by the soil engineer.

FOUNDATION RECOMMENDATIONS:

1. All footings shall be continuous.

2. All footing excavations shall be inspected and approved by the soil engineer, prior to the placement of rebar

or framework.

3. All exterior footings shall extend a minimum of <u>24 inches</u> below outside yard grade, while interior footings

shall extend a minimum of 24 inches below the concrete slab and sand blanket.

4. All continuous footings shall be reinforced with a minimum of 2-#5 rebar placed 1 in the top

and 1 in the bottom of the footing.

5. The concrete slab on grade shall be a minimum of 4 inches thick, and shall be reinforced with #3 rebar at

24 inches on center each way, (placed at mid-depth) and shall be underlain with a 4 inch sand blanket in which

an impervious membrane is embedded.

Order Number: 46953

Reference Number: 06-5873

FOUNDATION RECOMMENDATIONS:

6. Concrete slabs on grade (except patio slabs) shall be doweled into adjacent exterior footings using #3 rebar

dowels placed at 18 inches on center, embedded 24 inches into the footing and bent 36 inches into the concrete

slab.

7. If tile or other brittle surfacing is to be placed over concrete slabs a "slip sheet" is recommended to reduce

the potential for reflective cracking.

8. Concrete slabs on grade shall be placed at a maximum slump of 4 ½ inches to reduce shrinkage cracks. In

addition, shrinkage/control joints shall be placed at intervals not to exceed 10.0 feet center.

9. The finished structure shall be fitted with rain gutters and down spouts that effectively collect and

discharge all roof rain water run-off a minimum 10.0 feet away from the proposed structure.

10. Positive drainage shall be provided away from the proposed structure (2 percent minimum for 5.0 feet; 1

percent thereafter to a proper drainage device.

11. Based upon compliance with the above recommendations, a maximum safe soil bearing value of 1500 psf

may be assumed, with a one-third increase when considering wind or seismic movement.

12. Compliance with the above recommendations will reduce the potential for total settlement to 1 inch and

differential settlement to 3/4 of an inch in 30.0 feet.

Prepared by:

Brett J. Dolan Staff Engineer

TJD/cp

Respectfully

Coast Valley Testing, Inc.

Reviewed & Approved By:

Timothy J. Dolan, President

RCE \$3758 Expires 06-30-2006

Order Number: 46953

Reference Number: 06-5873

* * APPENDIX * *

Order Number: 46953

Reference Number: 06-5873

<u>APPENDIX</u>

MAXIMUM DENSITY-OPTIMUM MOISTURE DETERMINATIONS

Maximum Density-Optimum Moisture data was determined in the laboratory using the ASTM D-1557-91 Method of Compaction. The results are as follows:

SOIL TYPE	SOIL DESCRIPTION	DRY DENSITY (LBS/CU.FT)	MOISTURE (%)	
I	dark brown silty sand	121.5	11.5	
	curve points: (117.3 @ 9.9) (120.4 @ 12	.1) (113.2 @ 14.5)		
II	brown silty sand with gravel	128.0	10.0	
	curve points: (123.0 @ 7.8) (127.0 @ 9.6	5) (123.1 @ 12.1)		

II		FIELD	DENSITY SUMMAR	$\mathbf{\underline{Y}}$	
TEST NUMBER	DEPTH (ft)	SOIL TYPE	FIELD MOISTURE (%)	DRY DENSITY (lbs/cu. ft)	% OF MAXIMUM DRY DENSITY
1	1.5	I	13.2	96.5	79.4
2	1.0	I	18.9	97.8	80.5
3	1.0	I	16.9	101.3	83.4
4	1.5	II	10.8	102.1	79.8

III SOIL PARTICLE SIZE ANALYSIS (Values in percent passing)

I.

SIEVE SIZE	B -1 @ 1.0	B -1 @ 3.0	B -1 @ 5.0	B -1 (a) 7.0	B -1 (a) 10.0 (a)	B-1 b) 12.0 (a)	B -1 <u>0</u> 15.0
3/8	100	100	100	100	100_	100	100
No. 4	97	99	100	99	100	100	100
No. 8	92	95	97	. 97	100	99	100
No. 16	87	91	93	96	99	97	99
No. 30	80	84	84	82	92	96	95
No. 50	63	66	60	78	73	92	88
No. 100	45	47	40	70	47	88	81
No. 200	37	58	32	63	34	83	76

Page 8 Order Number: 46953 Reference Number: 06-5873

IV			<u>S(</u>	OIL PAR	TICLE S	SIZE ANA	<u>LYSIS</u>
MEC	HANI	CAL ANAL	YSIS (Values in	percent p	assing)	
SIEV	E	B -1	B -1	B -1	B -1	B -1	B- 1
SIZE	1 /	(a) 25.0	(a) 30.0	@ 35.0	(a) 40.0	(a) 45.0 (<u>a, 50.0</u>
3/8		100	100	100	100	100	100
No.	44	99	100	99	100	100	100
No.	8	97	100	96	95	99	98
No.	16	92	100	92	84	98	96
No.	30	85	99	83	68	96	91
No.	50	70	96	58	41	90	69
No.	100	57	90_	37	15	80	27
No.	200_	47	78	27	7	73	16

V.	V. <u>BY HYDROMETER</u>				
BORING	DEPTH	SAND	SILT	CLAY	SOIL
NO.	(FT)	(%)	(%)	(%)	DESCRIPTION
1	1.0	66	18	16	silty sand
1	3.0	64	20	16	silty sand
1	5.0	74	14	12	sand
1	7.0	34	38	28	clayey silt & sand
1	10.0	68	20	12	silty sand
1	12.0	16	50	34	clayey silt sand
1	15.0	38	38	24	clayey silt sand
1	25.0	52	27	21	clay sand
1	30.0	22	57	21	clayey silt
1	35.0	72	18	10	sand
1	40.0	88	8	4	sand
1	45.0	40	32	28	clayey silt sand
1	50.0	84	9	7	sand


Order Number: 46953

Reference Number: 06-5873

V <u>UBC EXPANSION</u>

The Expansion Soil Index was determined by the present UBC 29-A.

Expansion Determination Procedure and this index were found to $-18\,\,$ - Soil Type I



SANTA BARBARA STREET

Page 11 Order Number: 3

Reference Number: 06-5873

Earthquake Design Factor UBC 1997 Edition Chapter 16


	Design Values
Seismic Source	Mission Ridge Arroyo Parida Santa Ana Fault
Distance to Seismic Source	3 km ±
Seismic Zone	4
Table 16-I Seismic Zone Factor Z	0.40
Table 16-J Soil Profile Type	SD
Table 16-Q Seismic Coefficient Ca	0.44 Na
Table 16-R Seismic Coefficient Cv	0.64 Nv
Table 16-S Near Source Factor Na	1.2
Table 16-T Near Source Factor Nv	<u>1.46</u>
Table 16-U Seismic Source Type	B

Order Number: 46953

Reference Number: 06-5873

BORING LOG

Boring #1





Order Number: 46953

Reference Number: 06-5873

BORING LOG

Boring 2





ground water @ 7.0 feet

Order Number: 46953

Wright-SB St.cal

Reference Number: 06-5873

LIQUEFACTION ANALYSIS CALCULATION SHEET

Copyright by CivilTech Software www.civiltech.com (425) 453-6488 Fax (425) 453-5848

Licensed to Tim Dolan, Coast-Valley Testing Inc.

3/13/2006

2:07:01 PM

Input File Name: C:\Documents and Settings\tim\Desktop\liquifaction

report\Wright-SB St.liq

Title: Wright Subtitle: 222 Santa Barbara St.

Input Data:

Surface Elev.= Hole No.=B-1 Depth of Hole=50.0 ft Depth of water Table=7.0 ft Max. Acceleration=0.4 g Earthquake Magnitude=7.0

Hammer Energy Ratio, Ce=1.25
Borehole Diameter, Cb=1.15
Sampeling Method, Cs=1
SPT Fines Correction Method: Modify Stark/Olson
Settlement Analysis Method: Tokimatsu / Seed
Fines Correction for Liquefaction: Modify Stark/Olson
Fine Correction for Settlement: Corrected in Liquefaction
Average Input Data: Smooth

Depth	SPT	Gamma	Fines
ft		pcf	%
5.0 10.0 15.0 20.0 25.0 30.0 35.0 40.0 45.0 50.0	10.0 8.0 11.0 10.0 12.0 18.0 36.0 38.0 24.0 38.0	120.0 128.0 125.0 125.0 130.0 135.0 130.0 135.0 130.0	42.0 62.0 81.0 44.0 47.0 78.0 27.0 7.0 73.0 16.0

Output Results:

(Interval = 5.00 ft)

CSR Cal Depth ft	culation gamma pcf	n: sigma tsf	gamma' pcf	sigma' tsf	rd	CSR	fs (user)	CSRfs w/fs
5.00 10.00 15.00	120.0 128.0 125.0	0.300 0.610 0.926	120.0 65.6 62.6	0.300 0.516 0.677 Page 1	0.99 0.98 0.97	0.26 0.30 0.34	1.0 1.0 1.0	0.26 0.30 0.34

	20.00 25.00 30.00 35.00 40.00 45.00 50.00	125.0 130.0 135.0 130.0 120.0 135.0 130.0	1.239 1.557 1.889 2.220 2.532 2.851 3.182	Wrigh 62.6 67.6 72.6 67.6 57.6 72.6	t-SB St. 0.833 0.996 1.171 1.346 1.503 1.665 1.841	cal 0.95 0.94 0.93 0.89 0.85 0.81 0.77		umber: 46 ce Number 1.0 1.0 1.0 1.0 1.0		3
CRR7.5	CRR Cal Depth ft	culation SPT	from SP Cebs	T or BPT Cr	data: Cn	(N1)60	Fines %	d(N1)60	(N1)60f	
	5.00 10.00 15.00 20.00 25.00 30.00 35.00 40.00 45.00 50.00	10.00 8.00 11.00 10.00 12.00 18.00 36.00 38.00 24.00 38.00	1.44 1.44 1.44 1.44 1.44 1.44 1.44	0.75 0.85 0.95 0.95 0.95 1.00 1.00 1.00	1.70 1.39 1.22 1.10 1.00 0.92 0.86 0.82 0.77 0.74	27.21 27.28 36.50 24.32 26.50 41.43 49.88 45.04 43.05 42.90	42.0 62.0 81.0 44.0 47.0 78.0 27.0 7.0 73.0 16.0	8.88 13.68 18.24 9.36 10.08 17.52 5.28 0.48 16.32 2.64	27.21 27.28 36.50 24.32 26.50 41.43 49.88 45.04 43.05 42.90	0.32 0.33 2.00 0.27 0.31 2.00 2.00 2.00 2.00
	Factor Depth ft	of Safet sigC' tsf	y, – Ea CRR7.5 tsf	ırthquake Ksigma		ide= 7.0: MSF	CRRm	CSRfs w/fs	F.S. CRRM/CS	Rfs
	5.00 10.00 15.00 20.00 25.00 30.00 35.00 40.00 45.00 50.00	0.20 0.34 0.44 0.54 0.65 0.76 0.88 0.98 1.08	0.32 0.33 2.00 0.27 0.31 2.00 2.00 2.00 2.00 2.00	1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	0.32 0.33 2.00 0.27 0.31 2.00 2.00 2.00 1.99 1.95	1.19 1.19 1.19 1.19 1.19 1.19 1.19 1.19	0.39 0.39 2.39 0.32 0.37 2.39 2.39 2.39 2.37 2.33	0.26 0.30 0.34 0.37 0.38 0.39 0.38 0.37 0.36 0.34	5.00 1.29 5.00 0.88 * 0.96 * 5.00 5.00 5.00 5.00	_
	* F.S.< (F.S. i	1: Lique is limite	efaction ed to 5,	Potentia CRR is	l Zone. limited	(If about 2,	ove water CSR is	table: limited	F.S.=5) to 2)	
ds in.	Settlen Depth Settlen ft in.	nent of S CSRfs nent W/fs	Saturated F.S.	d Sands: -	(N1)60	Fines %	d(N1)60	(N1)60s	Dr %	ec %
	49.95	0.34	5.00		42.91	16.6	0.00	42.91	100.00	
0.000	0.000 45.00	0.000	5.00	-	43.05	73.0	0.00	43.05	100.00	
0.000	40.00	0.000	5.00		45.04	7.0	0.00	45.04	100.00	
0.000	35.00 0.000	0.000 0.38 0.000	5.00	-	49.88	27.0	0.00	49.88	100.00	
0.000	30.00 0.000	0.39 0.000	5.00	-	41.43	78.0	0,00	41.43	100.00	
1.030	25.00 0.006	0.38 0.148	0.96	-	26.50	47.0	0.00	26.50	82.65	
					Page 2					

	20.00	0.37	0.88	wri	ght-SB St. 24.32	cal 44.0		Number: 4	6953 er: 06-5873
1.167	0.007 15.00	0.807 0.34	5.00	_	36.50	81.0	0.00	36.50	100.00
0.000	0.000 10.00	1.048 0.30	1.29	-	27.28	62.0	0.00	27.28	84.23
0.173	0.001 7.00	1.082 0.26	1.40		26.08	50.0	0.00	26.08	81.81
0.000	0.000	1.129							

Settlement of Saturated Sands=1.129 in. qc1 and (N1)60 is after fines correction in liquefaction analysis ds is per each segment, dz=0.050 ft

ec7.5	Settlem Depth Cec ft in.	ent of D sigma' ec tsf in.	ry Sands sigC' ds tsf	(N1)60s Settlemo	CSRfs ent w/fs	Gmax tsf	g*Ge/	Gm %	g_eff %	
0.0178 0.0134	6.95 2.1E-4 5.00 1.6E-4	0.42 0.000 0.30 0.007	0.27	26.12 27.21	0.26	691.3 593.3	1.5E-4 1.3E-4	0.0276 0.0221	0.0192 0.0145	0.93

Settlement of Dry Sands=0.007 in. ds is per each segment, dz=0.050 ft

Total Settlement of Saturated and Dry Sands=1.136 in. Differential Settlement=0.568 to 0.750 in.

Units Depth = ft, Stress or Pressure = tsf (atm), Unit Weight = pcf, Settlement = in.

SPT BPT	Field data from Standard Penetration Test (SPT) Field data from Becker Penetration Test (BPT)
	Field data from Cone Penetration Test (CPT)
qc fc	Friction from CPT testing
Gamma	Total unit weight of soil
Gamma'	Effective unit weight of soil
Fines	Fines content [%]
D50	Mean grain size Relative Density
Dr	Relative Density
sigma sigma'	Total vertical stress [tsf]
sigma'	Effective vertical stress [tsf]
sigC' rd	Effective confining pressure [tsf]
rd	Stress reduction coefficient
CSR	Cyclic stress ratio induced by earthquake
fs	User request factor of safety, apply to CSR
w/fs	With user request factor of safety inside
CSRfs	CSR with User request factor of safety
CRR7.5	Cyclic resistance ratio (M=7.5)
Ksigma	Overburden stress correction factor for CRR7.5
CRRV	CRR after overburden stress correction, CRRv=CRR7.5 * Ksigma
MSF	Magnitude scaling factor for CRR (M=7.5)
CRRM	After magnitude scaling correction CRRm=CRRv * MSF
F.S.	Factor of Safety against liquefaction F.S.=CRRm/CSRfs
	Page 3

Order Number: 46953

Energy Ratio, Borehole Dia., and Sample Method Corrections Rod Length Corrections Cebs \mathbb{C} r Overburden Pressure Correction CnSPT after corrections, (N1)60=SPT * Cr * Cn * Cebs Fines correction of SPT (N1)60 after fines corrections, (N1)60f=(N1)60 + d(N1)60 (N1)60d(N1)60 (N1)60f Čq qc1 Overburden stress correction factor CPT after Overburden stress correction Fines correction of CPT dqc1 CPT after Fines and Overburden correction, qc1f=qc1 + dqc1 CPT after normalization in Robertson's method qc1f ac1n Fine correction factor in Robertson's Method KCCPT after Fines correction in Robertson's Method Soil type index in Suzuki's and Robertson's Methods (N1)60 after seattlement fines corrections qc1f IC (N1)60sVolumetric strain for saturated sands Settlement in each Segment dz Segment for calculation, dz=0.050 ft ec ds dz Shear Modulus at low strain gamma_eff, Effective shear Strain gamma_eff * G_eff/G_max, S Gmax g_eff g*Ge/Gm Strain-modulus ratio Volumetric Strain for magnitude=7.5 Magnitude correction factor for any magnitude ec7.5 cecVolumetric strain for dry sands, ec=Cec * ec7.5 ec

References:

NCEER Workshop on Evaluation of Liquefaction Resistance of Soils. Youd, T.L., and Idriss, I.M., eds., Technical Report NCEER 97-0022.

SP117. Southern California Earthquake Center. Recommended Procedures for Implementation of DMG Special Publication 117, Guidelines for Analyzing and Mitigating Liquefaction in California. University of Southern California. March 1999.


LIQUEFACTION ANAPLEYSIS Truer Number: 46953

Wright

Reference Number: 06-5873

Hole No.=B-1 Water Depth=7.0 ft

Magnitude=7.0 Acceleration=0.4g



CivilTech Software

- 70



Order Number: 46953

Reference Number: 06-5873

REPORT OF "R" VALUE TEST (Test Method ASTM D2844 / CALIF 301)

February 24, 2006

Coast Valley Testing

360 South Fairview, Suite A Goleta, California 93117

JOB No: 61243 LAB No: 60279

Depth: N/A

ATTENTION: Fred Best

PROJECT:

Coast Valley Testing-Misc. Tests

Material:

Brown Silty Sand w/ Traces of Gravel

Location: Sampled By: Wright Project

SPECS.

(California 202)

Client

Date Received:

SIEVE

SIZE

3"

2 1/2"

11/2"

1" 3/4" 2/21/06


% PASSING

GRADING ANALYSIS

Sample Type.

- #4 only + & - #4

"R" VALUE BY EXUDATION GRAPH



#200	33.0	(washed)		R-Value @ Equilibrium = 71			
#100	45		STABILOMETER VALUE 'R'	69	75	78	
#50	76		EXUDATION PRESSURE, psi	272	390	570	
#30	92		DRY DENSITY, pcf	119.7	120.7	121.5	
#16	96		MOISTURE @ COMPACTION %	11.2	10.2	9.2	
#8	98		INITIAL MOISTURE %	8.2	8.2	8.2	
#4	99		COMP. FOOT PRESSURE, psi	220	300	350	
3/8"	100		TEST SPECIMEN	A	В	С	. D /
1/2"							

REMARKS:

Copies:

1-Coast Valley Testing/Fred B.

1-File

Respectfully submitted,

U.S. LABORATORIES, INC.

Clarito Colocado Laboratory Supervisor Reviewed by:

Tom D. Williams Vice President